

New RepairBase Line Item additions for the 1-31-2017 Update

Heating & Cooling – Heat Pumps

- Replace Heat Pump - Packaged Through Wall Terminal Unit - 9000 BTU with electric heater - Does not Include Creating Wall Opening
- Replace Heat Pump - Packaged Through Wall Terminal Unit - 12000 BTU with electric heater - Does not Include Creating Wall Opening
- Replace Heat Pump - Packaged Through Wall Terminal Unit - 15000 BTU with electric heater - Does not Include Creating Wall Opening
- Replace Heat Pump - Split System - 14 SEER - 2 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 14 SEER - 3 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 14 SEER - 4 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 14 SEER - 5 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 16 SEER - 2 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 16 SEER - 3 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 16 SEER - 4 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 16 SEER - 5 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 18 SEER - 2 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 18 SEER - 3 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 18 SEER - 4 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set
- Replace Heat Pump - Split System - 18 SEER - 5 ton - Includes condenser, evaporator coil, Electric Heating Element, air handler and line set

Preservation & Maintenance – Securing – Doors & Windows

- Board up Window - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - First Window - up to 32 SF or 144 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Each Additional - Small - up to 8 SF or 72 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Each Additional - Medium - up to 16 SF or 96 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Each Additional - Large - up to 24 SF or 120 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Each Additional - Extra Large - up to 32 SF or 144 UI - 1/4" thick
- Board up Door - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Single Door - up to 32 SF or 144 UI - 1/4" thick
- Board up Door - Clear Polycarbonate - Secureview (tm) or Invisiboard (tm) type product - Double Door - up to 64 SF or 288 UI - 1/4" thick
- Board up Door - Clear Polycarbonate - Secureview (tm) type product - Operating Security Door - up to 32 SF or 144 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Purchased at National Retail Store - First Window - up to 32 SF or 144 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Purchased at National Retail Store - Each Additional - Small - up to 8 SF or 60 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Purchased at National Retail Store - Each Additional - Medium - up to 16 SF or 96 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Purchased at National Retail Store - Each Additional - Large - up to 24 SF or 108 UI - 1/4" thick
- Board up Window - Clear Polycarbonate - Purchased at National Retail Store - Each Additional - Extra Large - up to 32 SF or 144 UI - 1/4" thick

New RepairBase Line Item additions for the 1-31-2017 Update

Preservation & Maintenance – Securing – Doors & Windows

- Board up Door - Clear Polycarbonate - Purchased at National Retail Store - Single Door - up to 32 SF or 144 UI - 1/4" thick
- Board up Door - Clear Polycarbonate - Purchased at National Retail Store - Double Door - up to 64 SF or 288 UI - 1/4" thick
- Board up Door - Clear Polycarbonate - Purchased at National Retail Store - Operating Security Door - up to 32 SF or 144 UI - 1/4" thick
- Board up Window - Clear Acrylic - First Window - up to 32 SF or 144 UI - 1/4" thick
- Board up Window - Clear Acrylic - Each Additional - Small - up to 8 SF or 72 UI - 1/4" thick
- Board up Window - Clear Acrylic - Each Additional - Medium - up to 16 SF or 96 UI - 1/4" thick
- Board up Window - Clear Acrylic - Each Additional - Large - up to 24 SF or 120 UI - 1/4" thick
- Board up Window - Clear Acrylic - Each Additional - Extra Large - up to 32 SF or 144 UI - 1/4" thick
- Board up Door - Clear Acrylic - Single Door - up to 32 SF or 144 UI - 1/4" thick
- Board up Door - Clear Acrylic - Double Door - up to 64 SF or 288 UI - 1/4" thick
- Board up Door - Clear Acrylic - Operating Security Door - up to 32 SF or 144 UI - 1/4" thick