# New RepairBase Line Item additions for the 2-11-2016 Update

#### **Inspections - Inspections**

- Electrical Inspection Detailed Includes Complete Testing and Detailed Report Minimum Charge
- Electrical Inspection Basic Includes Visual and Minor Testing Minimum Charge

## Preservation & Maintenance - Inspections

- Electrical Inspection Detailed Includes Complete Testing and Detailed Report Minimum Charge
- Electrical Inspection Basic Includes Visual and Minor Testing Minimum Charge

#### Preservation & Maintenance – Securing – Doors & Windows

- Replace Window Well Half Round Metal Up to 3' Wide x 16" Projection x 36" Deep Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 4' Deep Good Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 4' Deep Better Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 4' Deep Best Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 6' Deep Good Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 6' Deep Better Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Rectangular Metal Up to 4' Wide x 3' Projection x 6' Deep Best Does Not Include Digging for Access, Cover or Disposal
- Replace Window Well Cover Half Round Up to 36" Wide x 18" Projection Good
- Replace Window Well Cover Half Round Up to 36" Wide x 18" Projection Better
- Replace Window Well Cover Half Round Up to 36" Wide x 18" Projection Best
- Replace Window Well Cover Rectangular Up to 48" Wide x 24" Projection Good
- Replace Window Well Cover Rectangular Up to 48" Wide x 24" Projection Better
- Replace Window Well Cover Rectangular Up to 48" Wide x 24" Projection Best

### Preservation & Maintenance – Securing - Floors

- Replace Registers Floor Up to 6" x 14" Economy
- Replace Registers Floor Up to 6" x 14" Good
- Replace Registers Floor Up to 6" x 14" Better
- Replace Registers Floor Up to 6" x 14" Best

# New RepairBase Line Item additions for the 2-11-2016 Update

## Preservation & Maintenance – Securing Pools & Spas

- Initial Treat & Shock Above-Ground Pool up to 200 S.F. Includes Chemicals for Algae & Mosquitos
- Monthly Treat & Shock Above-Ground Pool up to 200 S.F. Includes Chemicals for Algae & Mosquitos

#### Preservation & Maintenance – Winterization

- Repair Reduced Pressure Zone (RPZ) Valve Up To 1" Includes Removal, Repair, Reconnect and Test
- Repair Reduced Pressure Zone (RPZ) Valve Up To 2" Includes Removal, Repair, Reconnect and Test
- Repair Completely Rebuild Reduced Pressure Zone (RPZ) Valve Up To 1" Includes Removal, Repair, Reconnect and Test
- Repair Completely Rebuild Reduced Pressure Zone (RPZ) Valve Up To 2" Includes Removal, Repair, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 1/2" Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 3/4" Good Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 3/4" Better Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 1" Good Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 1" Better Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 1 1/2" Includes Removal, Reconnect and Test
- Replace Reduced Pressure Zone (RPZ) Valve 2" Includes Removal, Reconnect and Test